

LAND CORNER RECORD


Index: T-15	Corner: C1/4	State of Indiana - Hoosier National Forest		
Section: 27	Township: 7N	Range: 1E	P.M.: 2nd	County: Monroe
Coordinate:	Lat./N: 1371759.713	Long./E: 3147856.564	Datum: NAD83 IN West Zone, US Survey Feet	


CORNER HISTORY: (Chronological history of corner)

1.) Date of Survey:	Surveyor:	Monument:	Recording Information:	Monument Photograph:
8/3/1982	Ken Anderson L.S. #80040545	A 3" stamped brass disk set	USDA Forest Service Bedford, IN	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	Black Oak	14"	S30°W	7.30'
	Hickory	13"	N35°E	23.75'
	Tulip Poplar	9"	S28°E	23.75'
Record evidence of prior survey:				
2.) Date of Survey:	Surveyor:	Monument:	Recording Information:	
10/7/2008	Kevin Enright Monroe County Surveyor	A 3" stamped brass disk found	Monroe County Surveyor's Office Bk. 41, Pg. 45	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	Red Oak	22"	S36°W	5.89'
	Pignut Hickory	17"	N42°E	23.12'
	Yellow Poplar	22"	S47°E	23.23'
Record evidence of prior survey:	A metal post with a "SURVEY" sign is N87°W - 3.10'.			

ACCESSORIES: Bearing and distance from monument to witness object.

Reference Objects:	Object or Tree Species:	Diameter:	Bearing:	Distance:
	Black Oak* **	22"	S29°W	6.82'
	Pignut Hickory* **	18"	N42°E	23.76'
	Tulip Poplar* **	21"	S50°E	23.97'
** = no paint * = old blaze at base of tree	T-Post	N/A	N90°W	3.50'
Monument Found or Set:	An iron pipe with a 3" brass cap found 0.3' above grade.			

MONUMENT SKETCH	NARRATIVE REFERENCE:
	Monument is an iron pipe with a 3" brass cap found 0.3' above grade, a carsonite post is located 1.5' north of the monument, located 40' south of an east-west running drainage, on the northern side of and east-west running ridge, surrounded by mature forest, 400' S70°E of a one story house, +/- 200' east of a field with an electric rope fence, 40' S70°E of a large Poplar.

SECTION DIAGRAM	PERPETUATION RECORD:
 Corner Location = ●	The record monument was found undisturbed and maintained by remarking three existing bearing trees. Three existing bearing trees were recovered from a Monument Record by Kevin Enright, dated 10/7/2008. Three bearing trees were marked with a blaze, scribed B.T., bearing tree sign and mag nail. <i>Referenced on BRCJ survey recorded as InstNo.2018007752</i> <i>Accepted by the Monroe County Surveyor Review Board on August 6, 2019.</i>
Section: 27 T7N R1E	Prepared By: BRCJ (Project#3-0822) Date: 5/2018

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 27

Township: 7 North


Range: 1 East

Corner ID: Polk O-19

Monument Description & Remarks: 3" Brass Disk nothing stamped. Survey Sign 3ft above ground at pt. C


References On File: Raymond Graham survey, Old Dutch Ridge Rd (1999), on file in Surveyor Office

RECOVERY TIE DRAWING
Field Book 41 Page No. 45



- A - 3" Brass Disk
- B - S 36° W 5.89' to MAG nail in 22" Red Oak
- C - N 87° W 3.10' to Survey Sign on metal fence post
- D - N 42° E 23.12' to MAG nail in 17" Pignut Hickory
- E - S 47° E 23.23' to MAG nail in 22" Yellow Poplar

Not To Scale
Compass Bearing Magnetic North



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code, and the above data is given under my hand and seal this 16th day of September, 2008.

Kevin P. Enright

Administered by the Monroe County Surveyor Review Board

Date: 10/7/2008

